
Contents

Preface	xi
List of Notations	xv
Chapter 1. Modeling of Heat Transfer	1
1.1. The different modes of heat transfer	1
1.1.1. Introduction and definitions	1
1.1.2. Conduction	3
1.1.3. Convection	5
1.1.4. Radiation	6
1.1.5. Heat storage	8
1.2. Modeling heat transfer by conduction	8
1.2.1. The heat equation	8
1.2.2. Steady-state conduction	10
1.2.3. Conduction in unsteady state	21
1.2.4. The quadrupole method	29
1.3. The thermal properties of a material	37
1.3.1. Thermal conductivity	37
1.3.2. Thermal diffusivity	40
1.3.3. Volumetric heat capacity	41
1.3.4. Thermal effusivity	41
1.3.5. Conclusion	41

Chapter 2. Tools and Methods for Thermal Characterization	43
2.1. Measurement of temperature	43
2.1.1. Liquid column thermometer	43
2.1.2. Thermocouple	44
2.1.3. Thermistor	49
2.1.4. Platinum resistance	50
2.1.5. IR detector	50
2.1.6. IR camera	51
2.1.7. Choice of a measurement method	53
2.1.8. Data filtering	55
2.2. Tools for parameter estimation	56
2.2.1. Introduction	56
2.2.2. Quadrupole modeling	57
2.2.3. Dimensional analysis	61
2.2.4. Study of reduced sensitivity	64
2.2.5. Method for estimating parameters	70
2.2.6. Evaluation of the estimation error due to the measurement noise	72
2.2.7. Other sources of error	74
2.2.8. Validity domain of a model and estimation time interval	80
2.2.9. Choice of the temperature's origin	86
2.2.10. Conclusion	87
Chapter 3. Steady-State Methods	89
3.1. Introduction	89
3.2. Guarded hot plate	90
3.2.1. Principle	90
3.2.2. Hypotheses and model	91
3.2.3. Experimental design	92
3.2.4. Practice of the measurement	92
3.3. Center hot plate	92
3.3.1. Principle	92
3.3.2. Hypotheses and model	93
3.3.3. Experimental set-up	95
3.3.4. Practice of the measurement	96
3.4. Hot strip	99
3.4.1. Principle	99
3.4.2. Hypotheses and model	100
3.4.3. Experimental set-up	103
3.4.4. Practice of the measurement	103

3.5. Hot tube	105
3.5.1. Principle	105
3.5.2. Hypotheses and model	106
3.5.3. Experimental set-up	107
3.5.4. Practice of the measurement	110
3.6. Cut bar.	113
3.6.1. Principle	113
3.6.2. Hypotheses and model	114
3.6.3. Experimental set-up	115
3.6.4. Practice of the measurement	115
3.7. Calibrated tiny hot plate (CTHP)	121
3.7.1. Principle	121
3.7.2. Hypotheses and model	124
3.7.3. Experimental set-up	126
3.7.4. Practice of the measurement	127
3.8. Fluxmetric method	130
3.8.1. Principle	130
3.8.2. Hypotheses and model	131
3.8.3. Experimental set-up	133
3.8.4. Practice of the measurement	133
3.8.5. High temperature variant: CFM method	135
Chapter 4. Flux/Temperature Transient Methods	141
4.1. Introduction.	141
4.2. Infinite hot plate	141
4.2.1. Principle	141
4.2.2. Hypotheses and model	142
4.2.3. Experimental design	145
4.2.4. Practice of the measurement	146
4.2.5. Asymmetric setup.	149
4.3. Finite hot plate	152
4.3.1. Measuring temperature	152
4.3.2. Measurement of two temperatures	155
4.4. Hot wire	158
4.4.1. Principle	158
4.4.2. Hypotheses and model	159
4.4.3. Experimental setup	162
4.4.4. Practice of the measurement	162
4.5. Parallel hot wire	168
4.5.1. Principle	168
4.5.2. Hypotheses and model	169

4.5.3. Experimental setup	172
4.5.4. Practice of the measurement	174
4.6. Anistropic parallel hot wire	175
4.6.1. Principle	175
4.6.2. Hypotheses and model	177
4.6.3. Experimental setup	179
4.6.4. Practice of the measurement	180
4.7. Flash 1D.	182
4.7.1. Principle	182
4.7.2. Hypotheses and models	185
4.7.3. Methods for the estimation of diffusivity	197
4.7.4. Experimental setups	204
4.8. Flash 3D.	212
4.8.1. Principle	212
4.8.2. Hypotheses and model	214
4.8.3. Identification method	216
4.8.4. Example of an experimental setup	219
4.8.5. Practice of the measurement	223
4.9. Hot disk	228
4.9.1. Principle	228
4.9.2. Hypotheses and model	228
4.9.3. Experimental setup	233
4.9.4. Experimental study	234
4.10. Hot strip	237
4.10.1. Principle	237
4.10.2. Hypotheses and model	238
4.10.3. Experimental setup	244
4.10.4. Practice of the measurement	245
4.11. 3 ω Method	252
4.11.1. Principle	252
4.11.2. Hypotheses and model	253
4.11.3. Experimental setup	255
4.11.4. Practice of the measurement	256
4.12. Calorimetry	258
4.12.1. Differential calorimeter	258
4.12.2. Drop calorimeter	261
Chapter 5. Transient Temperature/Temperature Methods	263
5.1. Introduction	263
5.2. Planar three-layer	267
5.2.1. Principle	267

5.2.2. Hypotheses and model	269
5.2.3. Experimental set-up	273
5.2.4. Practice of the method	275
5.3. Cylindrical three-layer	276
5.3.1. Principle	276
5.3.2. Hypotheses and model	278
5.3.3. Experimental set-up	286
5.3.4. Experimental practice	287
5.4. Transient fin method	290
5.4.1. Principle	290
5.4.2. Hypotheses and model	291
5.4.3. Experimental set-up	294
5.4.4. Practice of the measurement	294
5.5. 4L method	295
5.5.1. Principle	295
5.5.2. Hypotheses and model	296
5.5.3. Estimation method	301
5.5.4. Experimental setup	301
5.5.5. Practice of the measurement	302
Chapter 6. Choice of an Adapted Method	305
6.1. Measurement advice	305
6.1.1. How many measurements?	305
6.1.2. Steady-state or transient mode?	306
6.1.3. What if the material is wet?	307
6.1.4. What if the material is semi-transparent?	308
6.2. Choice of method	310
6.2.1. Consolidated solid	311
6.2.2. Liquids	313
6.2.3. Powders	313
6.2.4. Small samples	313
6.2.5. Thin samples	314
6.2.6. High temperature measurement	314
Chapter 7. Analogies Between Different Transfers	315
7.1. Diffusion of heat by conduction	315
7.2. Diffusion of water vapor	316
7.3. Flow of a gas in a porous medium	318
7.4. Analogy between the different transfers	320

Chapter 8. Measuring the Transport Properties of Porous Media	323
8.1. Sorption measurement	323
8.1.1. Definitions	323
8.1.2. Sorption isotherms	325
8.1.3. Deductible physical characteristics of isotherms	330
8.1.4. Measurement methods	342
8.2. Water vapor diffusion coefficient	350
8.2.1. Diffusion equations	350
8.2.2. Steady-state measurement method	354
8.2.3. Isothermal transient measurement method	358
8.2.4. Non-isothermal transient measurement method	369
8.3. Permeability	375
8.3.1. Steady-state measurement	376
8.3.2. Draw down and pulse decay	378
8.3.3. Step decay	381
8.3.4. GRI	383
8.4. Porosity	392
8.4.1. Density measurement	392
8.4.2. Pycnometry measurement	392
8.4.3. Pore size distribution by thermal porosimetry	394
References	401
Index	413