
Contents

Preface	xi
Chapter 1. Various Properties of Crystals	1
1.1. Structure.	1
1.1.1. Introduction: crystallization energy	1
1.1.2. Attachment energy and layer energy	5
1.1.3. Superficial and molecular energies	5
1.1.4. Surface energy	6
1.1.5. Periodic chain and nature of faces	7
1.2. Form	8
1.2.1. Crystal system and habit.	8
1.2.2. Non-sphericity index (form index).	10
1.2.3. Nyvlt coefficients	13
1.2.4. The importance of form: porosity	13
1.2.5. Orthogonal rate and form development	14
1.2.6. Form modifier additives	15
1.3. Conclusions: crystal characteristics.	17
1.3.1. Form and specific surface	17
1.3.2. Chemical composition: hygroscopicity	18
1.3.3. Surface striations	19
1.3.4. Surface roughness	19
1.3.5. Attrition on drying: vitrification on grinding.	20
1.3.6. Surface concavity	21
1.3.7. Color	21
1.3.8. Flow behavior	21
1.3.9. Purity	22
1.3.10. Elasticity constants	22
1.3.11. Hardness, deformation and fracture	25

1.3.12. Fragility and ductility of crystals	27
1.3.13. Agglomeration in suspension	28
1.4. Attrition	31
1.4.1. Crystal hardness.	31
1.4.2. Fracture resistance	32
1.4.3. Attrition in a stirred vessel	33
1.5. PSD measurement of a crystalline population	34
1.5.1. Sifting.	34
1.5.2. The Coulter particle counter	34
1.5.3. Sedimentation	35
1.5.4. Image analysis.	36
1.6. Characteristics of a crystal population	36
1.6.1. Analytic expressions of particle size distribution	36
1.6.2. Mean size and solubility.	38
1.6.3. Coefficient of variation and attrition.	38
Chapter 2. Crystal Formation and Growth	39
2.1. Crystal formation	39
2.1.1. Primary nucleation	39
2.1.2. Crystallizer crust formation	43
2.1.3. Secondary nucleation	45
2.1.4. Metastable zone: supersaturation established slowly	48
2.1.5. Measurement of nucleation order n	48
2.1.6. Parameters influencing ΔT_{\max}	51
2.1.7. Practical study of the metastable zone (cooling).	53
2.1.8. Interpretation of latency time	55
2.1.9. Nucleation by vaporization: a practical aspect.	58
2.1.10. Nucleation in a crystallizer (calculation)	59
2.2. Energetic theory of face growth.	60
2.2.1. Hartmann and Bennema's theory (1980)	60
2.2.2. The presence of a solvent	61
2.2.3. Morphological importance and cleavage	61
2.2.4. Energy aspect and kinetic perspective.	63
2.3. Kinetic growth theories	63
2.3.1. General	63
2.3.2. Diffusion layer theory	64
2.3.3. Integration mechanisms	65
2.3.4. Fundamental parameters.	67
2.3.5. Growth of a K face	68
2.3.6. Bidimensional nucleation	70
2.3.7. Spiral growth	70
2.3.8. "Formation and spreading"	73

2.3.9. Diffusion–integration combination	74
2.3.10. Retrodiffusion of solvent.	75
2.3.11. Conclusions	76
2.3.12. Drawing crystal shapes.	78
Chapter 3. Crystallization in a Sugar Refinery	79
3.1. Theory of sugar crystallization	79
3.1.1. Growth mechanisms	79
3.1.2. Nucleation	80
3.1.3. Sugar purity and weight ratio	81
3.2. Orders of magnitude	82
3.2.1. Boiling delay	82
3.2.2. Diffusivity	83
3.2.3. Viscosity	83
3.2.4. Properties of crystallized sugar	84
3.3. Crystallization kinetics	85
3.3.1. Integration layer and diffusion layer combination.	87
3.4. Practice of sugar crystallization	87
3.4.1. The three crystallization techniques	87
3.4.2. Steps involved in industrial sugar crystallization	89
3.4.3. Seed preparation	90
3.4.4. Dewatering the massecuites.	91
3.4.5. Sugar refining	92
3.4.6. Thermal exchange data	92
Chapter 4. Crystallizers: Design and Dimensions	93
4.1. Introduction.	93
4.1.1. Qualities of a crystallized product	93
4.1.2. Crystallizers	93
4.1.3. Overall balance of the crystallizer population	94
4.1.4. Balance of population with attrition	96
4.1.5. Continuous homogeneous crystallizer with attrition	97
4.1.6. Batch with attrition	98
4.1.7. Agitation	99
4.1.8. Thermal exchange	100
4.2. Continuous homogenous crystallizer (CHC)	101
4.2.1. CHC definition	101
4.2.2. Crystallizer with a draft tube and an internal exchanger	102
4.2.3. Definition of draft tube	103
4.2.4. Classification zone	107
4.2.5. Purpose of classification.	109
4.2.6. Theory of CHC without attrition	110

4.2.7. Other values	111
4.2.8. Parameters to manage	116
4.2.9. CHC series without attrition	116
4.2.10. Operative relationship of a CHC without attrition	118
4.2.11. Installation possibilities of a CHC (population density)	120
4.2.12. Modulation of crystal content	124
4.3. Continuous forced circulation crystallizer (CFCC)	125
4.3.1. Description.	125
4.3.2. Residence time of crystals in the installation.	127
4.3.3. Entry level in a vaporization body	128
4.4. Crystallizer with fluidized bed	128
4.4.1. Presentation	128
4.4.2. Suspension and nucleation power	129
4.4.3. Calculation procedure	130
4.4.4. Laboratory study of a fluidized bed	135
4.5. Elutriation columns	136
4.5.1. General	136
4.5.2. Residence time of crystals in the column.	137
4.5.3. Calculation of different liquid flows.	138
4.6. Crystallizer piston with scraped walls	142
4.6.1. Description.	142
4.6.2. Calculation elements	142
4.7. Batch crystallizing: homogeneous vat	143
4.7.1. Design of batch crystallizers	143
4.7.2. Batch crystallization methods (presentation).	144
4.7.3. Seeding.	146
4.7.4. Controlled supersaturation	148
4.8. Vat population density	150
4.8.1. Constant nucleation without growth	150
4.8.2. Growth without nucleation	151
4.8.3. Nucleation with growth	151
4.9. Choice of crystallization	152
4.9.1. Cooling or vaporization	152
4.9.2. Continuous operation or batch operation	152
4.9.3. Agitation and thermal exchange	153
4.9.4. Fragile crystals	154
4.9.5. Very thick slurry	154
4.9.6. Granulometry spread	155
4.9.7. Crystal purity	155
4.9.8. Cascade of serial crystallizers	155
4.9.9. Particles in the slurry.	155
4.9.10. Possible crystal dimensions	156
4.10. Exploitation parameters	156

4.10.1. Order of magnitude for parameters	156
4.10.2. Residence time and supersaturation	157
4.10.3. Crystal content in slurry	158
4.10.4. Calculation of thermal transfer	159
4.10.5. Agitation and attrition	159
4.10.6. Incrustations	160
4.10.7. Checking the crystallization	161
4.10.8. Surface pollution	161
4.10.9. Precipitation by chemical reaction	164
4.11. Definition of a crystallization micropilot.	165
4.11.1. Use of the pilot	165
4.11.2. Definition of pilot exchanger tubes: velocity in the tubes	166
4.11.3. Velocity in the pilot tubes	166
4.11.4. Friction on the tube wall	167
4.11.5. How should the blockages in the pilot be avoided?	169
4.11.6. Conclusion	170
4.12. Crystallization at high temperature	170
4.12.1. General aim	170
4.12.2. The Verneuil method	171
4.12.3. The Czochralski method	171
4.12.4. The thermal gradient method	171
4.12.5. Film production	172
4.12.6. Crystals in the order of a millimeter	172
4.13. Calculation for continuous crystallizers	172
4.13.1. Cooling	172
4.13.2. Solvent vaporization	173
4.13.3. Establishing the thermal transfer parameters	174
Appendices	177
Appendix 1. Numerical Integration: The Fourth-order Runge–Kutta Method	179
Appendix 2. Resolution of Equations of the Third and Fourth Degree Searching for Dimensionless Groups	181
Bibliography	185
Index	193